

From: Rex A Schildhouse
987 Neighborly Lane
Ramona, CA 92065-2926 USA
raschildhouse@cox.net
Phone 760-803-5213

Date: Tuesday, May 5, 2020

I was using the Open Sign tutorial and made the following notes, provided so you can see my process,

Set the material size and XY Datum at the center for the design work,

Create the border with the center at X 0 and Y 0,

Create the second border,

To center a hole, hover over the first line, then hover over the second line, then move to the approximate center between those two points and Vectric will show a + sign,

To scale the size, you can hold Shift and then drag with the mouse,

Check the Material Set Up and move the reference to the lower left corner,

Make sure there is no offset,

Select the outer edge of the pocket, drag to capture all of the text with the left mouse button down,

Select V Carve Tool Path,

Define cutting depth,

Select Flat Depth of something like 0.20,

Select the V Bit tool for the first tool,

Select the Use Clearance Tool,

Select the 0.25 End Mill as a clearance tool,

Select the outer edge, select Profile and then the V Bit tool on the outside,

Select the outer edge, select Profile, and the 0.25 End Mill with a 0.20 offset outside,

Use Plunge,

Add tabs,

This is the exported image from VectricPro V10. It disagrees with the results.



This is an attempt in VectricPro V10 with Carbide Motion on my Shapeoko XXL.



This is the V-Carve Engraving Toolpath set up. The material is 3 1/2" high by 9" wide by 0.525" thick. The desired cut is 0.200.

V-Carve / Engraving Toolpath

Cutting Depths
 Start Depth (D) inches
 Flat Depth (F) inches

Tool: V-Bit (90.0° - 1/2")

Use Clearance Tools
 End Mill (1/4")

Tool-specific options
 Offset **Raster**
 Cut Direction
 Climb
 Conventional
 Raster Angle degrees
 Ramp Plunge Moves
 Distance inches
 Corner Sharpen

Use Vector Start Points
 Use Vector Selection Order

Safe Z inches
 Home Position X:0.00 Y:0.00 Z:1.00
 Project toolpath onto 3D model
 Vector Selection: Manual
 Name:

Edit Tool

Name
 Notes

Tool Type 

Geometry
 Units
 Diameter (D) inches
 Included Angle (A) degrees

No. Flutes

Cutting Parameters
 Pass Depth inches
 Final Pass Stepover inches %
 Clearance Pass Stepover inches %

Feeds and Speeds
 Spindle Speed r.p.m.
 Feed Units Chip Load inches
 Feed Rate inches/min
 Plunge Rate inches/min

Tool Number

Edit Tool

Name: End Mill (1/4")

Notes:

Tool Type: End Mill

Geometry

Units: inches

Diameter (D): 0.25 inches

No. Flutes: 2

Cutting Parameters

Pass Depth: 0.13 inches

Stepover: 0.1 inches 40 %

Feeds and Speeds

Spindle Speed: 16000 r.p.m

Feed Units: inches/min Chip Load: 0.0013 inches

Feed Rate: 40 inches/min

Plunge Rate: 10 inches/min

Tool Number: 1

OK Cancel



2D Profile Toolpath

Cutting Depths

Start Depth (D): 0.0 inches

Cut Depth (C): 0.2 inches

Show advanced toolpath options

Tool: V-Bit (90.0° - 1/2")

Select ... Edit ...

Passes: 2 Edit Passes ...

Machine Vectors...

Outside / Right

Inside / Left

On

Direction: Climb Conventional

Allowance offset: 0.0 inches

Do Separate Last Pass

Allowance (A): 0.0 inches

Reverse direction

Add tabs to toolpath

Length: 0.5 inches

Thickness: 0.1 inches

3D tabs Edit Tabs ...

Ramp Leads Order Start At Corners

Add ramps to toolpath

Type: Smooth Zig Zag Spiral

Specify Ramp ...

Ramp on Lead In

Distance: 1.0 inches

Angle: 20.0 degrees

Distance: 4.0 inches

Safe Z: 1.0 inches

Home Position: X:0.00 Y:0.00 Z:1.00

Project toolpath onto 3D model

Vector Selection: Manual Selector ...

Name: Wyatt Trial 2-Outside V Bit

Calculate Close

Toolpaths  

2D Profile Toolpath

Cutting Depths

Start Depth (D) inches

Cut Depth (C) inches

Show advanced toolpath options

Tool: End Mill (1/4")

Passes: 4

Machine Vectors...

Outside / Right

Inside / Left

On

Direction Climb Conventional

Allowance offset inches

Do Separate Last Pass

Allowance (A) inches

Reverse direction

Add tabs to toolpath

inches Length

inches Thickness

3D tabs

Ramp Leads Order Start At Corners

Add ramps to toolpath

Type Smooth Zig Zag Spiral

Specify Ramp ...

Ramp on Lead In

Distance inches

Angle degrees

Distance inches

Safe Z inches

Home Position X:0.00 Y:0.00 Z:1.00

Project toolpath onto 3D model

Vector Selection: Manual

Name:

This is the first pocket pass with a 0.250 End Mill, Tool 201 in the Shapeoko tool inventory. The cut is pretty close to 0.200", the value set in the tool path.



This is the V Carve pass with the Shapeoko Tool 301, 1/2" 90 degree V-bit. The cut is set to 0.200" and the actual cut is close to 0.400". The surprises include the depth, the steps at the bases of the letters, and the exterior dog bone issues on the corners.



This is the exterior V Bit cut, set to 0.200" and cutting to close to 0.400", which matches the inside V carve depth. It should leave a face surface, as shown in the Vectric image.



Final product, out of the work. The outline of the letters is not smooth, the bottom is not flat, the depth is beyond the 0.200" set in the toolpaths, and the dog bone issues on the issue V Carve.



A repeat of the Vectric image for comparison.



And, Vectric keeps saying that the final profile cut is going through the material while the material thickness is set to 0.525" and the cut depth is set to 0.525" as well. A bit frustrated. What setting, what process, is wrong?

Thanks,
Rex A Schildhouse
Lieutenant Commander, United States Navy, Retired and tired