

This is what I was trying to mimic. A branding iron, from Rockler, that just takes **TOO** long to heat up consuming **TOO** much power. Technology gives us lasers so I bought the Ortur and Lightburn. Poor photo, sorry.




I made three, one 2", one 3", one 4", all have the same type of issues. While the Lightburn image shows good alignment, troubles.


This is the 2" file - The roof is not proper or aligned, nor is it sitting on the rectangular frame. The saw and the hammer got trimmed. What happened to "2021"?




This is the Lightburn preview image.




This is the 3" file, roof issues, tool placment issues, 2021 issues.



This is the Lightburn preview of the 3" burn.



This is the 4" file, 'nuff said.



The burn patterns are speed of 75 and power of 40%. The 2" file is attached.

Any help? Thanks, Rex

raschildhouse@cox.net www.schildhouse.com